

Oil Field Environmental Incident Summary

Incident: 20130920135100 **Date/Time of Notice:** 09/20/2013 12:43

Responsible Party: BAYTEX ENERGY USA LTD

Well Operator: BAYTEX ENERGY USA LTD

Well Name: GERALYN MARIE 34-163-99H 1DQ

Field Name: AMBROSE

Well File #: 20569

Date Incident: 9/19/2013 **Time Incident:** 13:30

Facility ID Number:

County: DIVIDE

Twp: 163

Rng: 99

Sec: 34

Qtr: NW NW

Location Description: 50 ft. south of wellhead and under fence was observed an approximately 3 x 10 ft. area of oil

Submitted By: Joe Irvin

Received By:

Contact Person: Joe Irvin
600 17TH ST STE 1600 SOUTH
DENVER, CO 80202-5419

General Land Use: Pasture

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2.5	barrels	2.3	barrels		
Brine	2.5	barrels	2.3	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

Baytex Energy initiated emergency response of equipment and labor. Absorbent boom was immediately placed down gradient to stop flow and absorbent pads were placed to absorb visual oil. A trench was dug to allow for fresh water flushing of the affected area with all liquids promptly vacuumed up.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 9/20/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray from stuffing box leak left location. Follow-up is necessary.

Date: 9/25/2013 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 3:30 PM 9/25/13.

Entirety of spill cleaned up with no visible sign of oil anywhere on or off location.

No more follow up required.